



Bulletin Ref: 10_0009

Date: 13th July 2010

08841EUR-00 plug-on GSM Module replaced by 08841EUR-01

Cooper Security are pleased to announce an upgrade in performance on the 08841EUR-00 plug-on GSM module for the Homelink75 (07510), the new 08841EUR-01 uses the latest in GSM module technology and delivers improved network compatibility and signal strength.

The new unit has been designed to work with all variants of the 07510 core software at the versions shown below:

07510RUK-20	3.03.09 or later
07510REUR-xx	3.06.19 or later

In order to successfully install the above core software, the installed RF software needs to be version 3.06 or later. This RF software cannot be upgraded in the field.

To upgrade to the new core software version please visit www.coopersecurity.co.uk, log into touchpoint and locate the software in the 'downloads' section of the website. Alternatively contact your local Cooper Security sales or service representative who will be able to provide the software.

The 08841EUR-00 will be rendered obsolete by the introduction of the 08841EUR-01, all sales and orders should be made with the new part number. The outgoing GSM module is being made obsolete by its supplier and no further 08841EUR-00 will be available.

www.coopersecurity.co.uk

COOPER Safety

If you don't want to receive our emails, please click [here](#) to unsubscribe.